


Sensor Value drifting problem





Solutions Suggested by Sebastian
(R&D Expert, Wittenstein)

- Turn on the sensor, wait for an hour then re bias it and collect data
- It has to 'warm-up' before collecting data.
- But an isolation/box to remove the airflow effects.



Results

**Note: All results are after 60 min. of turn-on time*



15 seconds after rebias (after 1 hour of turn on in isolation)

