







# Drift Problem

- Problem with the z-axis reading ( $F_z$ )

# Idle forceps readings (mounted)

xPlot: Time (in S)  
yPlot: Force(in N)



Blue: Fz, Orange: Fx, Red: Fy

# Idle Sensor readings

Blue: Fz, Orange: Fx, Red: Fy

